

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080122-8

No. 11040

RECEIVED FROM

DATE REC'D. 1-26-59
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
6	322	000000	24019	0	0	00	00	03		
DRAWING NO. AND DESCRIPTION										QUANTITY
										ACCEPTED
732797 PLATE ALUMINUM										6
SHIP MEMO 85873										

RECEIVED BY
HMC 1069

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2741 E. COLORADO ST., PASADENA, CALIF.

No. 11042

RECEIVED FROM

DATE REC'D. 1-26-59
P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
1	322	000000	24036	0	0	00	00			
DRAWING NO. AND DESCRIPTION										QUANTITY
										ACCEPTED
732676 FOR ASS'Y										1
SHIP MEMO 85901										

RECEIVED BY
HMC 1069

BY

DATE

ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080122-8